



DP-1000

DETAIL DETERGENT

5L, 25L

USAGE

- Removing oil, soot and fat stains from metal surfaces.
- Used in machine wash systems for metals
- Effective removal of fats, various oils and other grime from metal surfaces

INSTRUCTIONS

- For a good result, the water temperature should be +60-80 C.
- Recommended time for grime removal is 5-15 min. Depends on the amount of grime

DOSAGE

- For machine wash on dirty aluminium and copper surfaces, dissolve 1-2L per 100L of water
- For exceptionally dirty aluminium and copper surfaces, dissolve 3-5L per 100L of water
- For other metals and their parts, dissolve 3-5 L per 100L of water

pH 13

WARNING

- If the substance gets in the eyes, rinse for 15 minutes with water and consult a doctor.
- Keep correctly sealed
- Keep out of reach of children
- Irrites the eyes and skin
- Wear safety goggles and gloves

INGREDIENTS

- <5% nonionic surfactant
- Potassium phosphates
- Sodium silicates
- Potassium hydroxide



Sõõbiv

Corrosive